Landfill Weight Station Slab Lift

Broome County, NY









Project Challenges	Solution	Support	Outcome
 Weigh Station Approach and Departure Slabs had settled causing unsafe traffic conditions. Unknown Soil Conditions. Weight Station had to remain operational during the repairs. 	 DCP Testing was conducted to determine soil conditions. URETEK 486 STAR structural polymer was used to stabilize the subsoils. URETEK 486 STAR structural polymer was used to lift the slabs and align the joints. 	 Broome County Resident Engineer's Office. Broome County Landfill maintenance Department. ZMK Construction 	 Soil was stabilized to depths determined by the DCP Test results. The approach / departure slabs were lifted and aligned to create safe traffic conditions. All work was completed in less than 2 days.