

Hills Pet Nutrition Distribution Center

LaVergne, TN



SITE



PROGRESS PICTURE

Project Challenges	Solution	Support	Outcome
<ul style="list-style-type: none"> • Rocking slabs when forklifts cross • Constant forklift loading traffic • No downtime allowed • Only other options included long downtime and interruption 	<p>Inject URETEK polyurethane to:</p> <ul style="list-style-type: none"> • Fill voids beneath slabs • Underseal slabs • Stabilize slabs 	<ul style="list-style-type: none"> • Pre-Estimate Meeting with Landlord and Tenant • Weekend work to minimize disruption • Live tests by tenant forklift operator to check slabs after injection 	<ul style="list-style-type: none"> • Minimal intrusion: Work performed in 5 hours with no disruption to business operations • Quick Cure: Open to traffic in 15 minutes • Under Budget: 40% under estimated budget