

Hillsborough Co. Evershine Lift Station

Tampa, FL



Project Challenges	Solution	Support	Outcome
<ul style="list-style-type: none"> • Poor soil conditions cause base of lift station and approach driveway to settle. • Stabilize base to prevent further settlement • Raise driveway approach 3" 	<ul style="list-style-type: none"> • Inject around pump station to stabilize • Inject under driveway to raise 3" back to grade 	<ul style="list-style-type: none"> • Hillsborough County Public Utilities 	<ul style="list-style-type: none"> • No downtime: All work performed in one day • No neighborhood disruption: No closure to traffic; all work completed during business hours