


Luxury Apartment Elevator Pit Sealing

Navarre, FL



Project Challenges	Solution	Support	Outcome
<ul style="list-style-type: none"> Other water sealing methods failed to stop infiltration. Over 5' of water needed to be dewatered. Remove all product from failed attempt to stop infiltration. 	<ul style="list-style-type: none"> De-water elevator pit Scan pit floor with radar to identify voids and utilities Inject chemical grout to displace water, fill voids and stop infiltration. 	<ul style="list-style-type: none"> Harrison Contracting dewatered elevator pits. Radar scan by Ground Penetrating Radar Services 	<ul style="list-style-type: none"> Minimal downtime: All work performed in two (4) hours. Slab under-sealed and infiltration stopped.