

# FishHawk Crossing Pipe Seal

## Tampa, FL



Project Challenges	Solution	Support	Outcome
<ul style="list-style-type: none"> <li>Failed joints in storm lines have caused manhole and roadway settlement</li> </ul>	<ul style="list-style-type: none"> <li>Inject around manhole and identified failed joints via video from Hillsborough County</li> <li>Displace water, fill voids, seal joints and stabilize soil around pipes</li> </ul>	<ul style="list-style-type: none"> <li>Hillsborough County Public Works</li> <li>Maintenance of traffic</li> </ul>	<ul style="list-style-type: none"> <li><b>No downtime:</b> All work performed in one day</li> <li><b>No neighborhood disruption:</b> Roadway stayed open as work was performed</li> </ul>