

# Marriott's Orlando World Center - Pool Orlando, FL



Project Challenges	Solution	Support	Outcome
<ul style="list-style-type: none"> <li>• Top to bottom renovation of one of Orlando's largest resorts</li> <li>• Engineering by Walter P. Moore discovered multiple voids underneath the pool</li> <li>• GWS was contracted by PLC Construction to fill voids with minimal renovation downtime</li> </ul>	<ul style="list-style-type: none"> <li>• Identified voids using GPRS services</li> <li>• Predetermined material amounts to eliminate potential pool collapse</li> <li>• Monitoring to assure voids completely filled</li> </ul>	<ul style="list-style-type: none"> <li>• Walter P. Moore Engineering</li> <li>• PLC Construction support to work with multiple sub-contractors on-site</li> </ul>	<ul style="list-style-type: none"> <li>• <b>No downtime:</b> All work performed in one day and on budget</li> <li>• <b>No construction disruption:</b> Renovation stayed on schedule</li> </ul>